

### 1. Insert instrument



**GDUnet #010001  
INSERT GMI**

### 2. Switch instrument ON



**GDUnet #010001  
SWITCH ON**



### 3. Test in progress





  3 - 6 min

### 4. Remove instrument



 **ALL TESTS PASS  
REMOVE GMI** 

 **FAILED TEST  
REMOVE GMI** 

# GDUnet

## Quick Operation Guide

Model without keypad



### 1. Enter Operator ID



Enter ID then #

### 2. Insert instrument



GDUnet #010001  
INSERT GMI

### 3. Switch instrument ON



GDUnet #010001  
SWITCH ON

### 4. Test in progress



### 5. Remove instrument



ALL TESTS PASS  
REMOVE GMI



FAILED TEST  
REMOVE GMI

